UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,847,926 B1

DATED

: January 25, 2005

INVENTOR(S) : Peter Ballam

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 18,

Line 65, should read -- circuit comprising the steps of --

Line 66, should read -- for a bi-directional pin of said model, applying signals to said --

Column 20,

Line 10, should read -- signal on said bi-directional pin will be super imposed over the --

Signed and Sealed this

Page 1 of 1

Seventeenth Day of May, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office